

Schwinn S500 charger issue.

Written by Johnsha

Sunday, 28 June 2009 10:06 - Last revised Wednesday, 01 July 2009

Question: Hi,I have a schwin s500 and the charger port do not work.How do i fix it,and what do i do?

Answer: You would need to purchase a new charge port and have the port installed or install it yourself. If you need to find a repair shop, or find parts, you can look at this: [Scooter Repair Shop](#)